Models:
OPTIKA PRO VIEW, OPTIKA LITE VIEW

Type:
SOFTWARES

Instructions:
Before proceeding with the SW installation, please check the table below "Software Function list" to identify the most suitable software.Enter the corresponding URL in your browser, and automatically you will download the software. Then double click on the setup.exe file to start the installation of the software. Please install also the driver if you find the "driver" folder.

DOWNLOAD LINKS

Windows
• http://www.optikamicroscopes.com/optikaproview.zip
• http://www.optikamicroscopes.com/optikaliteview.zip
• http://www.optikamicroscopes.com/optikavisionlite.zip

Linux
• http://www.optikamicroscopes.com/optikaLinux.zip

Mac OS
• http://www.optikamicroscopes.com/optikaMAC.zip

To combine Optika cameras with other softwares:
http://www.optikamicroscopes.com/directshowandtwainconnection.zip

SOFTWARE FUNCTION LIST

	FUNCTION	OPTIKA PRO VIEW	OPTIKA LITE VIEW
GENERAL	Operating system	Windows	Windows / MAC / Linux
	Simultaneous management of several cameras	X	X
	GUI (Graphical User Interface)	X	
	Report generator	X	
	Archiving	X	X
	Language — Catalan	X	X
	Language — Chinese (simpl.)	X	X
	Language — Chinese (trad.)	X	X
	Language — Korean	X	X
	Language — English	X	X
	Language — French	X	X
	Language — German	X	X
	Language — Indonesian	X	X
	Language — Italian	X	X
	Language — Japanese	X	X
	Language — Polish	X	X
	Language — Russian	X	X
	Language — Spanish	X	X
	Language — Thai	X	X
	Language — Turkish	X	X

	FUNCTION	OPTIKA PRO VIEW	OPTIKA LITE VIEW
MEASUREMENTS	Measurements on "live"	X	X
	Measurements on "captured"	X	X
	2D Measurements — Line	X	X
	2D Measurements — Angle	X	X
	2D Measurements — Parallel lines	X	X
	2D Measurements — Rectangle	X	X
	2D Measurements — Ellipse	X	X
	2D Measurements — Circle	X	X
	2D Measurements — Annulus	X	X
	2D Measurements — Arc	X	X
	2D Measurements — Curve	X	X
	2D Measurements — Polygon	X	X
	Particle count	X	
	Export to Excel	X	X

4083.Wifi and **4083.4** work with Vision Lite only.
C-E2 work with PROVIEW and LITEVIEW only.
Cameras with HDMI connection only, do not require any software; **C-HP** works with PROVIEW only, isn't compatible with Linux and MAC OS.

SOFTWARE FUNCTION LIST

IMAGE ACQUISITION	FUNCTION		OPTIKA PRO VIEW	OPTIKA LITE VIEW
	Simultaneous management of several cameras		X	X
	IMAGE acquisition		X	X
	Image formats	tiff	X	X
		jpg	X	X
		bmp	X	X
		png	X	X
		pcx	X	X
		jp2	X	X
		dcm	X	X
	IMAGE acquisition		X	X
	VIDEO formats	avi	X	X
		wmv	X	X
		mp4	X	X
		asf	X	X
		3gp	X	X
		mov	X	X
		h264	X	X
		h265	X	X
	Continuous automatic exposure		X	X
	Manual Exposure		X	X
	Mobile spot for exposure		X	X
	Resizable spot for exposure		X	X
	Colour acquisition		X	X
	Grey-scale acquisition		X	X
	Manual Time-Lapse		X	X
	Automatic Time-Lapse		X	X
	Fast Image Acquisition		X	X
	Focus Indicator		X	
	White Balance		X	X
	Black balance		X	
	Background correction		X	
	Dark Field Correction		X	X
	Image Enhancement		X	X
	Live Histogram		X	X
	Flip	Horizontal	X	X
		Vertical	X	X
	Rotate		X	

PROCESSING	FUNCTION	OPTIKA PRO VIEW	OPTIKA LITE VIEW
	Several function of image processing (filters)	X	
	Multiple image combining	X	X
	EDF (Extended Depth of Focus)	X	X
	Colour Combine (Multi-Fluorescence Imaging)	X	
	Shift Correction	X	
	HDR (High Dynamic Range)	X	
	Layer Management	X	X
	Text Overlay	X	X
	Ruler Overlay	X	X
	Measurement Overlay	X	X
	Grids	X	

4083.Wifi and **4083.4** work with Vision Lite only.
C-E2 work with PROVIEW and LITEVIEW only.
Cameras with HDMI connection only, do not require any software; **C-HP** works with PROVIEW only, isn't compatible with Linux and MAC OS.